



**Figure 2.** The arm has pivoted inward toward the cart and is compressing the circuit's inspiratory limb. This is possible because the articulating joint is below the level of the inspiratory port. If the joint is kept above the level of the port, this problem cannot occur. Another option is to mount the support arm on a different side of the ventilator, but this may not always be feasible.